

超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

日期: 2016年06月03日

測試報告

報告編號: UG/2016/50215

三商美福室內裝修股份有限公司

臺北市中山區建國北路2段145號3樓

以下測試之樣品係由申請廠商所提供及確認:

產品名稱: V313 化妝粒片板

申請廠商: 三商美福室內裝修股份有限公司

生產或供應廠商: 永森家具系統有限公司

產品型號: A268

2016年05月19日 送樣日期:

測試日期: 2016年05月19日~2016年06月03日

測試結果:

測試項目	CAS No	測試方法	測試結果		定量/偵測	單位
			最大值	平均值	極限	平位
甲醛釋出量	000050-00-0	本測試參考CNS 2215方法,以分光	0.729	0.680	0.0290	mg/L
		光度計(UV/VIS)檢測。				

備註:1.本報告不得分離,分離使用無效。

- 2. 若該測試項目屬於定量分析則以「定量極限」表示;若該測試項目屬於定性分析則以「偵測極限」表示。
- 3.低於定量極限/偵測極限之測定值以 "N.D."或" 陰性 " 表示。
- 4.CNS 2215普通合板甲醛釋出量標準如下:

F1 最大值: 0.4mg/L以下 平均值 0.3mg/L以下 F2 最大值: 0.7mg/L以下 平均值 0.5mg/L以下 F3 最大值: 2.1mg/L以下 平均值 1.5mg/L以下

- END -

Signed for and on behalf



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sqs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

台灣檢驗科技股份有限公司

No.38, Wu Chyuan 7th Rd., New Taipei Industrial Park, Wu Ku District, New Taipei City, 24890, Taiwan/ 新北市五股區新北產業園區五權七路38號 www.tw.sgs.com

頁數:1 of 2



超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

日期: 2016年06月03日

測試報告

報告編號: UG/2016/50215

三商美福室內裝修股份有限公司

臺北市中山區建國北路2段145號3樓

樣品照片

UG/2016/50215



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

台灣檢驗科技股份有限公司

No.38, Wu Chyuan 7th Rd., New Taipei Industrial Park, Wu Ku District, New Taipei City, 24890, Taiwan/新北市五股區新北產業園區五權七路38號

頁數:2 of 2